



Strategic Partnerships, Inc.
www.spartnerships.com



TEXAS
196 ARRA-funded DoD Projects
(\$305.7M) Completed or Under Way
by August 31, 2009.

If you are interested in having SPI point you to specific opportunities, contact Reagan Weil at 512.531.3900.

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Repair Training Area Unpaved Tank Trails	Army	Fort Bliss	60,000
Warrior in Transition (WT) Complex - Phase 1	Army	Fort Bliss	57,000
Repair War Road	Army	Fort Bliss	10,000
Repair Vehicular Pavements, Combat Aviation Brigade	Army	Fort Bliss	3,819
Repair Int/Ext, Building 250, East End, Family Readiness Ctr	Army	Fort Bliss	3,200
Repair Building 2930 Fitness Center--Floors, HVAC, Interior finishes, building envelope	Army	Fort Bliss	2,897
Repair Int/Ext, Building 515, Processing Center	Army	Fort Bliss	2,400
Replace Old HVAC and Provide Solar Daylighting - Buildings 1107 and 1108	Army	Fort Bliss	2,250
Repair Building 4797 Fitness Center--HVAC & Resurface Floor	Army	Fort Bliss	2,200
Hanger 11108: Repair / Upgrade Fire Extinguisher System	Army	Fort Bliss	2,000
Repair Windows and Insulation	Army	Fort Bliss	2,000
Repair Airfield Pavement to Eliminate Hazards Phase I	Army	Fort Bliss	1,800

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Repair Building 1441, Chapel 3	Army	Fort Bliss	1,500
Repair Building 1542, Chapel 2	Army	Fort Bliss	1,500
Repair Tac Equip Shop 2971 , Task Force Cram Elect, HVAC, Plumbing, Finishes	Army	Fort Bliss	985
Repair Tac Equip Shop 2462, 3/43bn,11 Bde Elect, HVAC, Plumbing, Finishes	Army	Fort Bliss	915
Repair Admin Building 241	Army	Fort Bliss	900
Repair Roof and Add Solar Panels to Building 777	Army	Fort Bliss	900
Repair Bn Hq Building 2918, 1/43 Bn, 11 BDE-Finishes, Elect, Doors, Windows	Army	Fort Bliss	895
Replace Deteriorated AC System With Hybrid (Building 11251)	Army	Fort Bliss	850
Repair Bn Hq Building 2913-Finishes, Elect, Doors, Windows	Army	Fort Bliss	829
Repair Tac Equip Shop 2466, 3/43 Bn,11 Bde Elect, HVAC, Plumbing, Finishes	Army	Fort Bliss	825
Repair Tac Equip Shop 2488,1/43 Bn,11 Bde Elect, HVAC, Plumbing, Finishes	Army	Fort Bliss	825
Repair Tac Equip Shop 1067, 93rd Mp Bn Elect, HVAC, Plumbing, Finishes	Army	Fort Bliss	810
Repair Bn Hq Building 2919 1/43 Bn, 11 BDE-Finishes, Elect, Doors, Windows	Army	Fort Bliss	768
Repair Bn Hq Building 2911 , 3/2 Bn, 11 BDE-Finishes, Elect, Doors, Windows	Army	Fort Bliss	695
Install A Precooling System and Switch to the 20mw Backup Generator At Chaffee and Jeb Stuart	Army	Fort Bliss	500

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Electrical Lighting Conservation -Occupancy Sensors/Timers	Army	Fort Bliss	450
Repair Building 28000, Div Headquarters, Building 28000, 1st CD	Army	Fort Hood	4,452
Deployment Infrastructure-Repairs to airfield Taxiways and Runways	Army	Fort Hood	3,000
Repair Failing Mechanical Equipment	Army	Fort Hood	3,000
Repair Roofs, Mechanical Systems, Electrical, Exterior Closures (Doors And Windows); Replace Steps and Ramps--14 buildings	Army	Fort Hood	3,000
Replace Outdated Chillers and Boilers	Army	Fort Hood	3,000
Repair Building 29016, Co Headquarters, Building 29016, 3/1 CD-Restore All Finishes and Systems	Army	Fort Hood	2,525
Repair Building 29007, Co Headquarters, Building 29007, 3/1 CD-Restore All Finishes and Systems	Army	Fort Hood	2,475
Repair Building 39008, Phys Fit Ctr, Building 39008, 13esc,-Restore All Finishes and Systems	Army	Fort Hood	2,377
Repair Building 29011, Co Headquarters, Building 29011, 3/1 CD-Restore All Finishes and Systems	Army	Fort Hood	2,275
Repair Building 29004, Co Headquarters, Building 29004, 3/1 CD-Restore All Finishes and Systems	Army	Fort Hood	2,270
Repair Building 91039, Vehicle Maintenance Shop, Building 91039, 504th	Army	Fort Hood	2,175
Replace Traffic Controls at 30 Intersections	Army	Fort Hood	2,000
Repair Building 29006, Brigade Headquarters, Building 29006, 3/1 CD, -Restore All Finishes and Systems	Army	Fort Hood	1,875
Repair Warehouse Building 49015-Restore All Finishes and Systems	Army	Fort Hood	1,800

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Repair Building 91026, Co Headquarters, Building 91026, 504th-Restore All Finishes and Systems	Army	Fort Hood	1,775
Repair Building 39016, Brigade Headquarters, Building 39016-Restore All Finishes and Systems	Army	Fort Hood	1,675
Repair Building 29013, BN Headquarters, Building 29013, 3/1 CD-Restore All Finishes and Systems	Army	Fort Hood	1,575
Repair Building 91027, BN Headquarters, Building 91027, 504th-Restore All Finishes and Systems	Army	Fort Hood	1,575
Repair Building 29015, BN Headquarters, Building 29015, 3/1 CD-Restore All Finishes and Systems	Army	Fort Hood	1,522
Repair Building 29014, Brigade Headquarters, Building 29014, 3/1 CD-Restore All Finishes and Systems	Army	Fort Hood	1,375
Repair Building 37005, BDE HQ Building -Restore All Finishes and Systems	Army	Fort Hood	1,200
Repair Deficiencies Found on Inspections of Dams	Army	Fort Hood	1,100
Replace and repair failed metering on electrical distribution system.	Army	Fort Hood	1,000
Repair Deficiencies Found on Inspections of Bridges	Army	Fort Hood	807
Replace Failed Fire Protection System, Hangar 7027	Army	Fort Hood	700
Restripe Base Roads for Bicycle/Pedestrian Traffic	Army	Fort Hood	594
Replace 180 Ton Chiller in Building 22028	Army	Fort Hood	500
Remediate Mold in Building 49020	Army	Fort Hood	250
Replace Failing Movable Divider Walls Ops Building 18000	Army	Fort Hood	100

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Barracks Building 904-- Replace HVAC, Plumbing, Electric, Finishes	Army	Fort Sam Houston	6,840
Repair Fire Alarm Systems, Various Buildings	Army	Fort Sam Houston	1,430
Replace HVAC controls; connect Building 4584 to Utility Management Control System (UMCS)	Army	Fort Sam Houston	1,428
Repair Classroom, Building 1396	Army	Fort Sam Houston	1,000
Design & Construct Fire Training Facility	Army	Fort Sam Houston	815
Design & Construct Laundry Room Addition to Barracks 904	Army	Fort Sam Houston	770
Design & Construct Laundry Room Addition to Barracks 905	Army	Fort Sam Houston	770
Design & Construct Laundry Room Addition to Barracks 907	Army	Fort Sam Houston	770
Design & Construct Laundry Room Addition to Barracks 915	Army	Fort Sam Houston	770
Design & Construct Laundry Room Addition to Barracks 916	Army	Fort Sam Houston	770
Design & Construct Laundry Room Addition to Barracks 920	Army	Fort Sam Houston	770
Design & Construct Laundry Room Addition to Barracks 929	Army	Fort Sam Houston	770
Design & Construct Laundry Room Addition to Barracks 930	Army	Fort Sam Houston	770
Repair Water System Controls	Army	Fort Sam Houston	725
Repair Culverts, Camp Bullis	Army	Fort Sam Houston	600

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Repair Bridges	Army	Fort Sam Houston	521
Connect Building 1377 to Utility Management Control System (UMCS)	Army	Fort Sam Houston	488
Repair Latrines, Building 1396	Army	Fort Sam Houston	310
Improve Marne Road, Camp Bullis	Army	Fort Sam Houston	220
Repair Heat Distribution Lines, Building 2248	Army	Fort Sam Houston	100
Repair Roof at Readiness Center	Army National Guard	Angleton	26
Repair Roof at Readiness Center	Army National Guard	Baytown	11
Repair Roof at Readiness Center	Army National Guard	Beaumont	29
Install Solar Panels	Army National Guard	Bergstrom - (Abia)	518
Install Solar Panels	Army National Guard	Bergstrom - (Abia)	518
Install Solar Panels	Army National Guard	Ellington Field	605
Repair Roof at Army Aviation Support Facility	Army National Guard	Ellington Field	26
Install Solar Panels	Army National Guard	Fort Sam Houston	196
Repair Roof at Readiness Center	Army National Guard	La Marque	322
Install Solar Panels	Army National Guard	Martindale - Army National Guard Aviation Support Facility	196

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Repair Roof at Readiness Center	Army National Guard	Pasadena	26
Repair Exterior Wall at Readiness Center	Army National Guard	Port Arthur	18
Repair Roof at Readiness Center	Army National Guard	Port Neches	36
Repair and Seal Aircraft Parking Apron Joints & Cracks	Air Force	Dyess AFB	2,050
Repair Electrical Distribution, Area C	Air Force	Dyess AFB	1,670
Repair Taxiway A Slabs	Air Force	Dyess AFB	1,500
Repair Gas Mains Phase 4	Air Force	Dyess AFB	1,198
Repair Taxiway C & D Shoulders	Air Force	Dyess AFB	1,056
Repair Runway Overruns 16 & 34	Air Force	Dyess AFB	958
Repair Billeting HVAC 7407 & 7409	Air Force	Dyess AFB	750
Install Heat Destratification Fans	Air Force	Dyess AFB	695
Repair 19 Additional Airfield Slabs	Air Force	Dyess AFB	553
Repair C-130 Apron Slabs	Air Force	Dyess AFB	500
Repair 6 Additional Lift Stations	Air Force	Dyess AFB	445
Repair Demand Ventilation Controls	Air Force	Dyess AFB	423

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Repair Hangar Doors, 5112	Air Force	Dyess AFB	246
Install Daylighting Control System	Air Force	Dyess AFB	151
Convert 8 TLaunch Facility Units to 4	Air Force	Dyess AFB	97
Repair Interior Dormitories 250 and 252 Phase 1	Air Force	Goodfellow AFB	1,461
Repair Interior Dormitories 255 and 257 Phase 2	Air Force	Goodfellow AFB	1,461
Antiterrorism, Relocate Parking Lot, Kearney Blvd	Air Force	Goodfellow AFB	733
Inst 12" Sewer PVC From New Dorm to Canberra St	Air Force	Goodfellow AFB	660
Kitchen/Shower Pans Billeting Building 711	Air Force	Goodfellow AFB	438
Convert 72 Rms to 36 Rms, Lodging B3311	Air Force	Goodfellow AFB	424
Repair Built Up Roof Training B 501 Incl Ext Lights	Air Force	Goodfellow AFB	406
Repair Apache Tarrace to Include Intersections	Air Force	Goodfellow AFB	388
Repair Comanche Tarrace Phase 2	Air Force	Goodfellow AFB	382
Connect to Energy Management Control System, Transportation B 3453/3420	Air Force	Goodfellow AFB	341
Replace Water Main Hydrants and Valvs N Ft Lancaster	Air Force	Goodfellow AFB	339
Repair Bath Rms Doors & Jambs Building 3311	Air Force	Goodfellow AFB	326

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Renovate Shower/Kitchens Dorm 700	Air Force	Goodfellow AFB	307
Paint Interior 144 Officer Dorm Rooms Building 700	Air Force	Goodfellow AFB	123
Repair Airfield Pavements Ph 2	Air Force	Kelly Field Annex	964
Repair Replace Roof Intel Ctr B2081	Air Force	Kelly Field Annex	218
Mtn (Paint) Floors In Hangar (B935)	Air Force	Kelly Field Annex	97
Mtn (Paint) Hush Hangar (B1147)	Air Force	Kelly Field Annex	30
Repair Water Main Line/Install Water Meters	Air Force	Lackland AFB	4,953
Repair Airfield Pavements Ph 1	Air Force	Lackland AFB	3,537
Antiterrorism Repair Perimeter Fence at Lta (Jsiva)	Air Force	Lackland AFB	1,920
Repair B7037 for Military Uniform Sales	Air Force	Lackland AFB	1,571
Antiterrorism Repair Perimeter Fence at Main Base West (Jsiva)	Air Force	Lackland AFB	1,225
Repair/Replace Road @ M-16 Small Arms Ranges	Air Force	Lackland AFB	1,029
Repair/Runway Rubber Removal	Air Force	Lackland AFB	736
Repair/Const Dept of Homeland Security Training Lab	Air Force	Lackland AFB	733
Repair Range Road	Air Force	Lackland AFB	552

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Antiterrorism Repair Perimeter Fence at Main Base East (Jsiva)	Air Force	Lackland AFB	538
Antiterrorism Repair Perimeter Fence at Security Hill (Jsiva)	Air Force	Lackland AFB	536
Repair 433rd Airfield Apron	Air Force	Lackland AFB	429
Paint Exterior Dli Dorms	Air Force	Lackland AFB	412
Repair Road, Hughes to Haby's Rd	Air Force	Lackland AFB	314
Repair Barnes Road (Luke to SeLaunch Facilityridge)	Air Force	Lackland AFB	238
Construct Bus Shelters - Main Base Nw	Air Force	Lackland AFB	221
Repair Aircraft Washrack Apron (A20c), B 10792, Kelly Field Ann	Air Force	Lackland AFB	204
Seal Cracks and Repair Joints In Roads Basewide	Air Force	Lackland AFB	202
Replace Roof Mini-Mall, B 10345	Air Force	Lackland AFB	187
Paint Interior Recruit Dorm B 9110	Air Force	Lackland AFB	162
Idq-Repair Roof Dormitory B10800	Air Force	Lackland AFB	145
Paint Interior Fitness Center and Playground Equip., B2418	Air Force	Lackland AFB	119
Paint Exterior Stairwells Dorms-B/10547 and B/10540 &B9410	Air Force	Lackland AFB	116
Repair Dormitory Roof System (7460)	Air Force	Lackland AFB	91

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Repair-Roof Temp Living Qtrs B3610/12/14/16/18	Air Force	Lackland AFB	78
Paint Exterior of Dorms 1st Floor	Air Force	Lackland AFB	64
Repair Roofs at Intel Ctr Buildings 2060, 2059, and 1208	Air Force	Lackland AFB	62
Construct Intel Ctr Parking Lot Entrance, B 2081	Air Force	Lackland AFB	48
Paint Interior (1st Fl) Dormitory Building 10656	Air Force	Lackland AFB	48
Paint Interior (2nd Fl) Dormitory Building 10656	Air Force	Lackland AFB	48
Paint Interior (3rd Fl) Dormitory Building 10656	Air Force	Lackland AFB	48
Paint Exterior of Hangar (B935) and Operations (B934)	Air Force	Lackland AFB	44
Mnt (Paint) Interior of Fisher House III (B3865)	Air Force	Lackland AFB	39
Paint Exterior Dormitory Building 10070	Air Force	Lackland AFB	37
Renovate Security Forces Building 187	Air Force	Lackland Training Annex	575
Repair/Upgrade Fitness Test & Training Track - Medina (138)	Air Force	Lackland Training Annex	269
Repair/Replace Fan Coil Units In Chapel, B 10338	Air Force	Lackland Training Annex	257
Repair Patrol Rd, Ph1	Air Force	Lackland Training Annex	39
Repair Airfield Pavements, Maintenance Access Apron	Air Force	Laughlin AFB	2,291

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
IDIQ-Repair Aerospace Ground Equipment Airfield Parking	Air Force	Laughlin AFB	322
Repair Liberty Drive at Main Gate Ph 1 of 5	Air Force	Laughlin AFB	272
Sr-Const Cover Over Parking/Uoq - A	Air Force	Laughlin AFB	271
Repair Liberty Drive Main Gate to Arkansas Ph 2 of 5	Air Force	Laughlin AFB	245
Remove/Prevent Corrosion, Water Towers--B280,282	Air Force	Laughlin AFB	201
Energy-Install Capacitor System for Power Factor Conversion	Air Force	Laughlin AFB	80
Repair Roof, Air Traffic Control Tower, B309	Air Force	Laughlin AFB	71
Repair Military Working Dog Kennel Floor	Air Force	Laughlin AFB	65
Repair/Replace West Switching Stations	Air Force	Randolph AFB	2,422
Repair/Replace East Switching Sta.	Air Force	Randolph AFB	2,361
Repair Roof Multi Basewide	Air Force	Randolph AFB	996
Repair Pavement H Street	Air Force	Randolph AFB	792
Replace K Circuit Multi Admin Fac B860, B861, B862	Air Force	Randolph AFB	584
Roof Replace Roof Admin B745	Air Force	Randolph AFB	565
Replace Transformers and Switches B 738	Air Force	Randolph AFB	482

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Replace Aircraft Fire Fighting Foam Diesel Engines, B50	Air Force	Randolph AFB	410
Repair Pavement J Street and 5th St	Air Force	Randolph AFB	399
Replace K Circuit Multi Admin Fac B860, B861, B862 Ph II	Air Force	Randolph AFB	292
Repair Pavement & Add Lane South Gate	Air Force	Randolph AFB	277
Replace Roof Admin B241	Air Force	Randolph AFB	234
LED Airfield Lighting	Air Force	Randolph AFB	209
Re-Lamp Admin Buildings 3, 241, 75, and 76	Air Force	Randolph AFB	28
Repair Sewage Systems Tech Trng Building 920	Air Force	Sheppard AFB	1,094
Repair Tech Trng Hangar Doors - 1010/1060/1090	Air Force	Sheppard AFB	1,009
Replace Built-Up Roof, Building 239	Air Force	Sheppard AFB	806
Repair to meet Codes, Fire Suppression Sys, Tech Training Buildings 1040/1080/1090	Air Force	Sheppard AFB	772
Repair Water Mains Ave J, Bridwell - 21st	Air Force	Sheppard AFB	519
Replace 12" Water Main, Bridwell to 80th St	Air Force	Sheppard AFB	428
Add to & Alter Munitions Admin Facility 2204	Air Force	Sheppard AFB	376
Extend Fire Protection Water Loop Combat Skills Training Area	Air Force	Sheppard AFB	246

<i>Project Title</i>	<i>Component</i>	<i>Installation</i>	<i>Estimated Cost (\$000s)</i>
Landscape Hunters Mesa Common Areas	Air Force Family Housing	Dyess AFB	140
Construct Rubberized Surface Playground Area-A	Air Force Family Housing	Dyess AFB	30
Construct Rubberized Surface Playground Area-B	Air Force Family Housing	Dyess AFB	30
Repair Dental Clinic #3 Building 39033	TRICARE Management Agency	Fort Hood	4,358

*Source: U.S. Department of Defense